This Information Is Provided By

CBTricks.com

Cobra 138XLR / 139XLR Technical Bulletin 1208A

Liability of damages to any equipment is the sole responsibility of the user! Downloading, viewing, or using any information provided on these pages automatically accepts the user to the terms of this agreement!

Modifications are provided for information purposes only!

Supporters of CBTricks.com paid for the hosting so you would have this file.

CBTricks.com is a non-commercial personal website was created to help promote the exchange of service, modification, technically oriented information, and historical information aimed at the Citizens Band, GMRS (CB "A" Band), MURS, Amateur Radios and RF Amps.

CBTricks.com is not sponsored by or connected to any Retailer, Radio, Antenna Manufacturer or Amp Manufacturer, or affiliated with any site links shown in the links database. The use of product or company names on my web site is not endorsement of that product or company.

The site is supported with donations from users, friends and selling of the Site Supporters DVD's to cover some of the costs of having this website on the Internet instead of relying on banner ads, pop-up ads, commercial links, etc. Thus I do not accept advertising banners or pop-up/pop-under advertising or other marketing/sales links or gimmicks on my website.

ALL the money from donations is used for CBTricks.com I didn't do all the work to make money (I have a day job). This work was not done for someone else to make money also, for example the ebay CD sellers.

All Trademarks, Logos, and Brand Names are the property of their respective owners. This information is not provided by, or affiliated in any way with any radio or antenna Manufacturers.

Thank you for any support you can give.

For information on how to Support CBTricks.com http://www.cbtricks.com/support/

COBRA FIELD BULLETIN

SUBJECT: Revision of Bulletin 1208. TR43 & TR44 Burnout.

SYMPTOM: No transmit on A.M. or S.S.B. TR43 found defective.

SOLUTION: 1. Remove R204 10 ohm $\frac{1}{2}$ watt resistor.


- 2. Remove C-181 47µf capacitor.
- 3. Remove C-232 180pf capacitor.
- 4. Change R-180 from 56 ohm 2 watt to 100 ohm 1 watt,

 Dynascan part number 002-001-6-101.
- 5. Change R205 from 1 ohm $\frac{1}{4}$ watt to 4.7 ohm $\frac{1}{4}$ watt,

 Dynascan part number 002-104-5-479.
- 6. Add a 47 ohm $\frac{1}{4}$ W resistor Dynascan part number 002-104-5-470. Schematic symbol to be R204. From base to ground of TR43 final.
- 7. Add a 470 ohm ½ watt resistor Dynascan part number 002-104-5-471 schematic symbol 216 from base to ground of TR-44 driver.
- 8. Change R181 to 100 ohms I watt. Dynascan part number 002-001-6-101.
- 9. Change D51 from a KB162 W diode to a MV-1Y diode Dynascan part number 004-175-9-001. White dot indicates cathode side.
- 10. Change D52 from a KB162W to a MV-ly Dynascan part number 004-175-9-001. White dot indicates cathode side.
- 11. Set driver idle current to 40mA at TP3, TP4 by adjusting control VR15.
- 12. Set final idle current to 15mA at TP1, TP2 by adjusting control VR16.

NOTE:

- This modification should be done on all units that come in for warranty repair.
- This modification is applicable up to Production number 70003500 on the Cobra 138XLR and up to Production number 70003000 on the Cobra 139XLR units. Beyond these numbers, already contain this modification.



DDW/jg 6-21-77 #1208A

Page 2 of 2