This Information Is Provided By

CBTricks.com

Cobra 138XLR / 139XLR Technical Bulletin 1210A

Liability of damages to any equipment is the sole responsibility of the user! Downloading, viewing, or using any information provided on these pages automatically accepts the user to the terms of this agreement!

Modifications are provided for information purposes only!

Supporters of CBTricks.com paid for the hosting so you would have this file.

CBTricks.com is a non-commercial personal website was created to help promote the exchange of service, modification, technically oriented information, and historical information aimed at the Citizens Band, GMRS (CB "A" Band), MURS, Amateur Radios and RF Amps.

CBTricks.com is not sponsored by or connected to any Retailer, Radio, Antenna Manufacturer or Amp Manufacturer, or affiliated with any site links shown in the links database. The use of product or company names on my web site is not endorsement of that product or company.

The site is supported with donations from users, friends and selling of the Site Supporters DVD's to cover some of the costs of having this website on the Internet instead of relying on banner ads, pop-up ads, commercial links, etc. Thus I do not accept advertising banners or pop-up/pop-under advertising or other marketing/sales links or gimmicks on my website.

ALL the money from donations is used for CBTricks.com I didn't do all the work to make money (I have a day job). This work was not done for someone else to make money also, for example the ebay CD sellers.

All Trademarks, Logos, and Brand Names are the property of their respective owners. This information is not provided by, or affiliated in any way with any radio or antenna Manufacturers.

Thank you for any support you can give.

For information on how to Support CBTricks.com http://www.cbtricks.com/support/

COBRA FIELD BULLETIN

SUBJECT:


REVISION OF BULLETIN #1210. TR-5 SHORTING.

SYMPTOM:

VERY LOW RECEIVE SENSITIVITY OR NO RECEIVE AT ALL. TR-5 FOUND SHORTED.

SOLUTION:

- 1) REPLACE TR-5,2SC1730, DYNASCAN PART NO 176-073-9-001. IF A 2SC1730 IS NOT AVAILABLE A 2SC784 DYNASCAN PART NO 176-026-9-001 MAY BE USED.
- 2) ADD 2 DIODES CONNECTED TO THE UNUSED TERMINAL OF L-3 IN PARELLEL ANODE TO CATHODE. IS2473, DYNASCAN PART NO 151-035-9-001 OR IS1555 DYNASCAN PART NO 151-030-9-001 DIODES CAN BE USED.



NOTE:

- 1) THIS MODIFICATION SHOULD BE DONE ON ALL COBRA 139XLR'S IN FOR IN-WARRANTY REPAIR AND WHEN THE CUSTOMER COMPLAINS ON THE COBRA 138XLR. IF TR-5 CHECKS GOOD ADDING THE DIODES IS ALL THAT IS NECESSARY.
- 2) THIS MODIFICATION IS APPLICABLE UP TO PRODUCTION NO 70029001 ON THE COBRA 138XLR AND UP TO PRODUCTION NO 70020001 ON THE COBRA 139XLR. UNITS BEYOND THESE NUMBERS ALREADY CONTAIN THIS MODIFICATION.

DDW/pc 6-21-77 #1210A