This Information Is Provided By CBTricks.com

Cobra 32XLR Technical Bulletin 1221

Liability of damages to any equipment is the sole responsibility of the user! Downloading, viewing, or using any information provided on these pages automatically accepts the user to the terms of this agreement!

Modifications are provided for information purposes only!

Supporters of CBTricks.com paid for the hosting so you would have this file.

CBTricks.com is a non-commercial personal website was created to help promote the exchange of service, modification, technically oriented information, and historical information aimed at the Citizens Band, GMRS (CB "A" Band), MURS, Amateur Radios and RF Amps.

CBTricks.com is not sponsored by or connected to any Retailer, Radio, Antenna Manufacturer or Amp Manufacturer, or affiliated with any site links shown in the links database. The use of product or company names on my web site is not endorsement of that product or company.

The site is supported with donations from users, friends and selling of the Site Supporters DVD's to cover some of the costs of having this website on the Internet instead of relying on banner ads, pop-up ads, commercial links, etc. Thus I do not accept advertising banners or pop-up/pop-under advertising or other marketing/sales links or gimmicks on my website.

ALL the money from donations is used for CBTricks.com I didn't do all the work to make money (I have a day job). This work was not done for someone else to make money also, for example the ebay CD sellers.

All Trademarks, Logos, and Brand Names are the property of their respective owners. This information is not provided by, or affiliated in any way with any radio or antenna Manufacturers. Thank you for any support you can give.

> For information on how to Support CBTricks.com http://www.cbtricks.com/support/



Cobra Communications

COBRA FIELD BULLETIN - # 1221

SUBJECT: Improvement in Cross Modulation Characteristics of Cobra 32 XLR with N.B. on.

SYMPTOM: On the Cobra 32 XLR the Noise Blanker cuts out the signal and noise on weak stations on antenna only.

SOLUTION: 1) Add 33pf ceramic cap. between IC2 pin 2 to T4 (cut foil add cap) Dynascan P/N 020-157-9-003.

2) Add 2200 pf ceramic cap between IC2 pin 4 to pin 5 on the foil side of the board. Dynascan P/N 020-088-9-007.

NOTE: This modification should be done on all units in for warranty repair when the customer complains. Eliminates previous cross mod degradation introduced by the Noise Blanker.

DW/ks 1/11/78 # 1221