

Consumer Response Group

6500 W. Cortland Street * Chicago, IL 60707 * Phone: 773-889-8870 * FAX: 773-622-2269

January 11, 2006

Page 1 of 2

TECHNICAL SERVICE BULLETIN 10046

MODEL(S): 150GTL, 200GTL

DESCRIPTION: After adjusting the squelch control, sometimes received signals may sound choppy due to the squelch repeatedly opening and closing.

ACTION: Change R47 to a 2.2 meg-ohm resistor. This will increase the squelch hystersis.


See page 2 for the location of R47.

ADJUSTMENTS: 1. Turn the squelch control fully clockwise.

- 2. Inject a 1500µV signal to the antenna connector (1KHz, 30% modulation).
- 3. Adjust RV2 until the squelch just opens.

NOTES: None.

<u>150 GTL</u>



<u>200 GTL</u>

