This Information Is Provided By

CBTricks.com

Pace Service Bulletin #0010

Liability of damages to any equipment is the sole responsibility of the user! Downloading, viewing, or using any information provided on these pages automatically accepts the user to the terms of this agreement!

Modifications are provided for information purposes only!

Supporters of CBTricks.com paid for the hosting so you would have this file.

CBTricks.com is a non-commercial personal website was created to help promote the exchange of service, modification, technically oriented information, and historical information aimed at the Citizens Band, GMRS (CB "A" Band), MURS, Amateur Radios and RF Amps.

CBTricks.com is not sponsored by or connected to any Retailer, Radio, Antenna Manufacturer or Amp Manufacturer, or affiliated with any site links shown in the links database. The use of product or company names on my web site is not endorsement of that product or company.

The site is supported with donations from users, friends and selling of the Site Supporters DVD's to cover some of the costs of having this website on the Internet instead of relying on banner ads, pop-up ads, commercial links, etc. Thus I do not accept advertising banners or pop-up/pop-under advertising or other marketing/sales links or gimmicks on my website.

ALL the money from donations is used for CBTricks.com I didn't do all the work to make money (I have a day job). This work was not done for someone else to make money also, for example the ebay CD sellers.

All Trademarks, Logos, and Brand Names are the property of their respective owners.

This information is not provided by, or affiliated in any way with any radio or antenna Manufacturers.

Thank you for any support you can give.

For information on how to Support CBTricks.com http://www.cbtricks.com/support/



PDSR-1
Date Of Issue 5-20-76

24049 SOUTH FRAMPTON AVENUE, HARBOR CITY, CALIFORNIA 90710 • TEL. (213) 325-1290 • TWX 910 347 7310 PATHCOM HRBO

SERVICE BULLETIN # 0010

CB 123A SENSITIVITY

During the past few months, our manufacturing facility in Japan has been having to subsitute a few transistors in the reciever section of the 123A. This change in production has increased the recievers sensitivity in some production runs. With an increase in sensitivity, unfortunately, noise has been increased in some units.

For the user wishing quieter operation, we have a very simple field modification.

This modification can be performed two ways:

MODIFICATION #1

Remove capacitor C38 (30 pf) from the base of Q2 and replace it with a 1 to 3 pf capacitor. In addition, change R35 (3300 ohms) to a 1500 ohm 1/4 watt resistor.

OR

MODIFICATION #2

Condition #1 If R18 is 470 ohms, add a 6800 ohm 1/4 watt resistor in parallel with R14, 22,000 ohm located across T4. Also add a 68,000 ohm 1/4 watt resistor in parallel with R43.

Condition #2 If R18 is 1000 ohms, add a 6800 ohm 1/4 watt resistor in parallel with R14, 22,000 ohm resistor across T4 only.

This change will decrease the recievers sensitivity, but should keep it around .5 microvolt for 10 db S + N.