


## TECHNICIAN NOTE

Here is a helpful hint to eliminate HF Audio noise from your speaker. Install two 47MF 25WVDC filters across the speaker. A SPST toggle switch may be used to switch CAP in and out.




### ROYCE 1-632 CLARIFIER MODIFICATION

- 1-Cut R-48.
- 2-Cut white wire from clarifier. Replace white wire with a jumper to a 9 volt source. Clarifier is now unlocked.

### TELSTAT 1240 LAFAYETTE

POWER: Eliminate D-5 in power supply.

MODULATION: Cut D-311.



FREQ. COUNTER MOD.  
TO SECRET CB DUMMY LOAD.