

CROSS-REF. (Cont.)

Pearce Simpson Tiger Mark II, try #148 - Hygain 2680/81.

Pearce Simpson Tomcat 23B, try #95 - American Electronics 76-501/601  
almost identical.

Pennys 981-6237, try #236 - Sears 934.38062700, PCB identical.

RCA 14T100, try #90 - Fulcomm Mdl. 2300

Romar CB-7000, try #106 - Nuvox CB-7000

Royce 609, try #266 - Pace 8003

Sears 23-PLL CM2378SL, try #236 - Sears 934.38062700, almost identical to  
23 ch. unit.

Sears CM-2378A, try #236 - same as above, almost identical.

Sears CM-2378SA, try #236 - same as above, Identical.

.....

Got carried away, but went through my files and added all that I had to Emil's  
list also. Hope this saves someone the time/expense of trying to find SAMS  
for a certain unit.

.....

For 858 SSB Chassis (40 Ch., not those converted at factory from 23 to 40)!

TRY #207 - Realistic TRC-457/458, and #176 - President Adams: These two have  
the most complete schematics/PCB 'stuffings' of all.

---

PACE 8041, (SM5118-PLL)

Tune up: Peak L6, L7, L8, L10, L13, L14. AMC Defeat - CR15.

---

LAKE 400 AM Mobile, (MC145106P-PLL)

If you want to try Fo modification on this unit see info on Palomar SSB-500.

---

UPDATES:

PACE 8155, (MM55107N-PLL); PACE 2300-C, (NPC5107-PLL)

Fo Modification is identical in both of these units:

26.325-26.685MHz, selector pos. 1-32, - open Pin 9

26.695-27.005MHz, selector pos. 5-32, - open Pin 10

---