

### CROSS-REFERENCE

Try SAMS #285, Pace 8093; if in a bind for service data. It is not exact but close for the following: SBE LCMS 4, ROYCE 642.

Also may be roughly used as parts locator for the PACIFIC 800 SSB, "have been told is sort of close - better than nothing".

---

#### GE 3-5826A SSB Mobile (IC7131-PLL) Slide Mod. by T.J.

No SAMS on this unit...need schematic or Service Manual to copy for our files. (SCB)....

Tune adjustments: AM Power - RV7, ALC - RV2, AMC - RV6, TX Mtr - RV4,  
RX Mtr - RV3.

No Fo Mod given on this unit - (try Pin 20, logic shift should yield (another 40 upper Fo's - in the 0's. (B.W.)

Slide Mod:

1. Remove D44 from PCB.
  2. Remove D3, replace with a Super Diode, or combination of 'S-D' and Super Slide. (See Vol. 19, page 53.) Will probably need a large slide if you do the above suggested Fo Mod.
  3. Trace White/Pink wire on clarifier control back to PCB, remove at the board carefully. Re-route to positive side of C165 and solder on the etch side of PCB. (If it won't stretch that far, remove at control and use another piece of wire.)
  4. Center clarifier knob and adjust following for center Fo's:  
CT1 - USB; CT2 - LSB; CT4 - AM.
- 

### H E L P

A bunch of the Pacific 800 SSB units are sitting around needing the following parts: IC-1 (SL-1611C), and IC-2 (SL-1612C).

Haven't been able to cross-reference to ECG, etc. Anyone have anything on these 2 chips, pass along the info....