
Motorola MOCAT 40 - Microphone Replacement

When the microphones on these units go bad, you have a <u>BIG</u> problem! Since they have a built-in preamp powered by the radio itself, can't be replaced by a stock microphone. Also from what I understand Motorola doesn't make/have replacement parts!

A CA-50 Cobra Power Microphone can be utilized by rewiring it to the original Motorola microphone cable as below:

- 1. A. Carefully remove microphone cord from CA-50 head, clean off the push-to-talk switch soldering points.
 B. Remove Blue and Yellow wires (discard).
- 2. Carefully remove Motorola cable from microphone head clean the ends of cable as will be reused.
- 3. Follow wiring diagram below using Motorola cable/plug, and CA-50 microphone head.



Now the radio will power the CA-50 and have plenty of audio.

THIS IS A PROVEN MODIFICATION......

SPECIFIC TUNEUP

Fulcomm 2330 (23 Ch.) No SAMS #:

TX: Peak I463, I465, I451, and I441 for max forward on Ch 12; also
I464 coils may be spread/compressed to tune. 2SC1975 is a 15W/2A
Final.

VR481-AMC. VR491-TX Mtr. VR181-Sq Rng. VR151-RX Mtr. VR152-RF Gain.