

## **Consumer Response Group**

6500 W. Cortland Street \* Chicago, IL 60707 \* Phone: 773-889-8870 \* FAX: 773-622-2269

November 18, 2003 Page 1 of 2

## TECHNICAL SERVICE BULLETIN 10029

MODEL(S): 25 LTD ST

**DESCRIPTION:** Squealing on receive when using an external speaker.

ACTION: Install a 0.01µF ceramic disk capacitor between pin 4 of IC1 and ground. Install

the capacitor on the foil side of the main PCB as shown on page 2.

**ADJUSTMENTS:** None.

**NOTES:** None.

