



EQUIPMENT AFFECTED

Rechargeable Battery Unit, Part No. 239-0128-001

REASON FOR REVISION

To prevent possible shorting of the recharging circuitry when the battery unit is plugged into an AC outlet with a metal cover.

REVISION

1. Center the masking tape on each exposed rivet head on the top of the battery pack header assembly.
2. Completely cover the masking tape and overlap approximately 0.062 inch all around the edges with a 4:1 ratio of epoxy and hardener.

PARTS REQUIRED

<u>PART NUMBER</u>	<u>DESCRIPTION</u>
042-0181-230	Bakelite epoxy cement, C8 resin
042-0181-231	Hardener

CHANGE ACTION

This change has been incorporated in all current production runs.