

REALISTIC TRC-47  
12KC SLIDER FOR SSB

- (1) Remove the unit from its cabinet and locate the left terminal on the clarifier control as shown.
- (2) Unsolder or cut this wire loose from the board and solder a 3.3 UH RF choke in series with it.

NOTE: The RF choke can be the miniature type as space is limited in this type of unit. If it is desired to slide the AM side, the same procedure can be followed on the right side of the clarifier control.

