

Ed. Notes:

The EXPORT ROUNDUP will be cut back in Vol. 20, and only the NEW units not previously listed will be mentioned. - Unless a vast amount of information "materializes". (Remember that the Roundup is not indexed!) I am trying to work out an arrangement with some distributors for obtaining information. But they are slow about sending manuals, even though sent back the same day received.

Contributors - I utilize the information received on a first in, first used basis, most of the time. If more complete information is received from another person use it instead. By complete I mean: Manufacturer; Model-Name; PLL type; Frequency Range of operation; Mode of operation (AM - FM - SSB - CW - ?); Specification Sheet; and Schematic. Ideal information is 'Original Owner's Manual and Schematic. (I am sitting on an 'Export' line-up procedure now, because the Transmit portion wasn't sent in?). Also have gotten away from repeating ('new') modifications on previously published information, when all they amount to is: re-write or using a different type of switch arrangement, but is still basically the same! It must be new - the only type of repeat type of information will be on a breakthrough to accompany the original.

ALL - Problems, service information is published. As is any buys on discontinued items by R/S.--(The problem here is that by the time we get into print, stuff is hard to find - still say we needed that combination "Wanted-Sell-Trade" Newsletter...but? (Note: I tried it myself separately from Secret CB; and only went \$85 in the hole; with printing/mailing costs!) Well, maybe someday it will come about...as parts for older units are getting hard to find. RE: Plastic front for 858 Grant is an example; Factory doesn't have!

Later, goin' Fishin' --- back in August.