


FORMAC 700, "TALKBACK MODIFICATION"

by R.M.

This modification was employed on S/N 500194 which had previous "Power/Echo" modification, (see Vol. 23, page 36).

For this reason the TONE switch was used for modification after 'hardwiring' for desired tone.



NOTE: Switch is viewed looking down on chassis from etch side.
Wired as such the 'Talkback' feature is ON, when switch is in up position (High).

ALERT: GALAXY 2100, PROBLEM

TRANSMIT COMES AND GOES..... CHECK FL-3, HAVE FOUND BAD IN UNITS. REPLACEMENT SHOULD CURE PROBLEM. (J.V.)