This Information Is Provided By

CBTricks.com

Pace Service Bulletin #0004

Liability of damages to any equipment is the sole responsibility of the user! Downloading, viewing, or using any information provided on these pages automatically accepts the user to the terms of this agreement!

Modifications are provided for information purposes only!

Supporters of CBTricks.com paid for the hosting so you would have this file.

CBTricks.com is a non-commercial personal website was created to help promote the exchange of service, modification, technically oriented information, and historical information aimed at the Citizens Band, GMRS (CB "A" Band), MURS, Amateur Radios and RF Amps.

CBTricks.com is not sponsored by or connected to any Retailer, Radio, Antenna Manufacturer or Amp Manufacturer, or affiliated with any site links shown in the links database. The use of product or company names on my web site is not endorsement of that product or company.

The site is supported with donations from users, friends and selling of the Site Supporters DVD's to cover some of the costs of having this website on the Internet instead of relying on banner ads, pop-up ads, commercial links, etc. Thus I do not accept advertising banners or pop-up/pop-under advertising or other marketing/sales links or gimmicks on my website.

ALL the money from donations is used for CBTricks.com I didn't do all the work to make money (I have a day job). This work was not done for someone else to make money also, for example the ebay CD sellers.

All Trademarks, Logos, and Brand Names are the property of their respective owners.

This information is not provided by, or affiliated in any way with any radio or antenna Manufacturers.

Thank you for any support you can give.

For information on how to Support CBTricks.com http://www.cbtricks.com/support/



Date of Issue 9-1-75 PDSR-1

24049 SOUTH FRAMPTON AVENUE, HARBOR CITY, CALIFORNIA 90710 • TEL. (213) 325-1290 • TWX 910 347 7310 PATHCOM HRBO

SERVICE BULLETIN # 0004

MOBILE INSTALLATION HINTS

To those readily familiar with transistorized CB radio equipment, there is a tendency to install and operate the equipment without reading the details in the instructions manual. In particular, the following precautionary notes should be strictly observed.

 $\underline{\text{DO}}$ $\underline{\text{NOT}}$ attempt to connect the power cord to a primary source with the power switch on. Determine system polarity before connection.

DO NOT use a ground type speaker.

DO NOT plug in external PA speaker with the power on.

DO NOT key the transmitter without an antenna connected.

 $\underline{\text{DO}}$ $\underline{\text{NOT}}$ replace the fuse with any other type.

<u>NOT</u> attempt alignment of the transmitter to the antenna. Loss of modulation power and inefficient operation possibly resulting in transistor burnout will occur unless the factory prescribed tuning procedure is followed. Maximum efficiency of an installation will result when the antenna has a VSWR of less than 1.5:1. The antenna should be tuned, trimmed, or replaced, if necessary, to achieve this.

No other single part of the system can be as significant a factor in complete success or total failure of performance as the antenna installation. It is advisable not to experiment, but rather to use performance proven antennas. Many new "miracle" antennas appear on the market from time to time, but most of them disappear after a short period. Bumper mounts are inadvisable because of their extreme directivity. Consult your dealer for the correct type and installation.

The length of the cable from the antenna to the radio is, contrary to popular belief, not important. *What is important is that the antenna have low VSWR. If a shortened type of antenna is used, it is mandatory that the VSWR be checked. A PACE P5403A VSWR bridge or similar instrument can be used. If the VSWR is greater than 1.5:1, the antenna must be adjusted in accordance with the manufacturer's instructions. If the antenna is a 1/4 wave nonadjustable type, the cable connections and the ground to vehicle at the antenna mount should be checked.

POWER CONNECTIONS

The transceiver is designed to operate from a nominal 12 volt DC source. This unit may be installed in vehicles which have either positive or negative ground. Since all passenger vehicles and most trucks use 12 volt negative ground systems, the power line is filtered for best noise limiting under negative ground installations, with the fuse in the red (+) line.

^{*} Recommend as short as possible cable to reduce attenuation.

NOTE:

When installing in 12 volt positive ground systems, the red lead is still connected to the positive terminal and the black lead to the negative terminal. This means your grounded lead is fused, which will still give you the same over-current protection.

For noise problems refer to Service Bulletins #73102 and #7471.