




Lethally high voltages are present inside the amplifier.  
Use Caution when servicing.



Disclaimer:  
Although the greatest care has been taken while compiling these documents,  
we cannot guarantee that the information is 100% correct.  
Copyright © 2004 B. Bolin