




- Q101, Q107, Q301: MPS9426 (C), 2SC1923
- Q102, Q103: BF964
- Q104, Q108: 2SK19 JF1033S
- Q105: MPS9623 (I) 2SC373
- Q106: MPS9623 (I)
- Q110, Q204, Q207: MPS9631
- Q201, Q202, Q203: MPS9634
- Q205: MPS9416
- Q109, Q206: MPS9681
- Q302: 2SC1957, 2SC2314, 2SC1678
- Q303: 2SC1306, 2SC495, 2SC2078
- Q401: 2SD525 OR 2SD1062 (R)
- Q402: 2SA950 (Y)
- Q403, Q404: 2SC1815 (Y)



NOTES: A SERVICE PERSONNEL TO USE ONLY REPLACEMENT PARTS THAT HAVE THE CRITICAL CHARACTERISTICS RECOMMENDED BY THE MANUFACTURER.

B SERVICE PERSONNEL MUST MAKE LEAKAGE-CURRENT OR RESISTANCE MEASUREMENTS TO DETERMINE THAT EXPOSED PARTS ARE ACCEPTABLY INSULATED FROM THE SUPPLY CIRCUIT BEFORE RETURNING THE APPLIANCE TO THE CUSTOMER.

C SAFETY PRECAUTIONS TO BE OBSERVED DURING SERVICING WHEN TESTING WITH EXPOSED ELECTRICAL PARTS.